

AD-A079 027

GANNETT FLEMING CORDDRY AND CARPENTER INC HARRISBURG PA F/G 13/13  
NATIONAL DAM INSPECTION PROGRAM. LAKE HENRY DAM (NDI ID NUMBER --ETC(U)  
APR 79 A C HOOKE DACW31-79-C-0015

UNCLASSIFIED

1 OF 1  
AD  
A079027

NL

END  
DATE  
FILMED  
2-80

DOC

ADA 079027

Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0015

(15) DACW31-77-C-0015

(1)

1281

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY

PENNSYLVANIA

(6) National Dam Inspection Program.  
LAKE HENRY DAM  
(NDI ID <sup>Number</sup> PA-00366  
DER ID <sup>Number</sup> 35-16),  
~~PENNSYLVANIA GAS AND WATER COMPANY~~  
Susquehanna River Basin, Lake Run,  
Lackawanna County, Pennsylvania.  
PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

Prepared by (10) Albert Charles/Hook

GANNETT FLEMING CORDDRY AND CARPENTER, INC.  
Consulting Engineers  
P.O. Box 1963  
Harrisburg, Pennsylvania 17105

For

DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21203

(11) APR 1979

REPRODUCTION OF THIS REPORT: ALL DDC  
REPRODUCTIONS MUST BE IN BLACK AND WHITE

411004 Em

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY  
PENNSYLVANIA

LAKE HENRY DAM

NDI ID No. PA-00366  
DER ID No. 35-16

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

APRIL 1979

CONTENTS

| <u>Description</u>   | <u>Page</u> |
|--|-------------|
| SECTION 1 - Project Information. . . . .                                   | 1           |
| SECTION 2 - Engineering Data . . . . .                                     | 6           |
| SECTION 3 - Visual Inspection. . . . .                                     | 8           |
| SECTION 4 - Operational Procedures . . . . .                               | 10          |
| SECTION 5 - Hydraulics and Hydrology . . . . .                             | 12          |
| SECTION 6 - Structural Stability . . . . .                                 | 15          |
| SECTION 7 - Assessment, Recommendations, and<br>Remedial Measures. . . . . | 17          |

|                |                |
|----------------|----------------|
| Accession File |                |
| NDIS           | 35-16          |
| DER            | 35-16          |
| LAKE           | LAKE HENRY DAM |
| DATE           | APR 1979       |
| BY             |                |
| REVIEWED       |                |
| APPROVED       |                |
| FILED          |                |
| A              |                |

## PLATES

| <u>Plate</u> | <u>Title</u>      |
|--------------|-------------------|
| 1            | Location Map.     |
| 2            | Plan.             |
| 3            | Typical Sections. |
| 4            | Profiles.         |
| 5            | Outlet Works.     |

## APPENDICES

| <u>Appendix</u> | <u>Title</u>                   |
|-----------------|--------------------------------|
| A               | Checklist - Engineering Data.  |
| B               | Checklist - Visual Inspection. |
| C               | Hydrology and Hydraulics.      |
| D               | Photographs.                   |
| E               | Geology.                       |

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT OF GENERAL CONDITION

AND

RECOMMENDED ACTION

Name of Dam: Lake Henry  
NDI ID No. PA-00366/DER ID No. 35-16

Owner: Pennsylvania Gas and Water Company

State Located: Pennsylvania

County Located: Lackawanna

Stream: Lake Run

Date of Inspection: 27 October 1978

Inspection Team: Gannett Fleming Corddry and  
Carpenter, Inc.  
Consulting Engineers  
P.O. Box 1963  
Harrisburg, Pennsylvania 17105

Based on visual inspection, available records, calculations and past operational performance, Lake Henry Dam is judged to be in good condition. The existing spillway can pass 60 percent of the Probable Maximum Flood (PMF) without overtopping of the dam. The spillway capacity is rated as inadequate.

If the embankments were raised 0.7 foot to their design elevation, the dam could pass the PMF with 0.05 foot of freeboard. The spillway capacity would then be rated as adequate. A low area between the two embankments acts as an auxiliary spillway.

There is no stability analysis for the embankments. There is no evidence of significant problems threatening the embankments. The spillway weir is judged to be stable.

The following measures are recommended to be undertaken by the Owner, in approximate order of priority, without delay.

- (1) Raise the embankments to their design elevation.
- (2) Extend the riprap on the upstream embankment slopes to the top of the dam. This should be accomplished in a manner to acceptably flatten the upstream slopes.
- (3) Grade the low area between the embankments to provide better hydraulic control. Provide erosion protection at the abutments of both embankments.
- (4) Fill the hole at the end of the left embankment. Continue to observe the area. If changes are noted, take immediate remedial action.
- (5) Remove the brush in the spillway channel and the trees at the toes of the embankment slopes.
- (6) Repair the mortar in the spillway walls and the paving in the spillway apron.
- (7) Monitor the seepage at the end of the outlet works pipe. The embankment should be inspected for seepage with the pool at spillway crest level. If changes are noted, take appropriate action.
- (8) Ensure that a proper size plug is available to provide upstream closure at the outlet works.
- (9) Determine if adequate access is available from the right abutment of the right embankment. If it is not, improve the access road.

In addition, it is recommended that the Owner modify his operational procedures as follows:

- (1) Develop a detailed emergency operation and warning system for Lake Henry Dam.
- (2) Provide round-the-clock surveillance of Lake Henry Dam during periods of un usually heavy rains.
- (3) When warnings of a storm of major proportions are given by the National Weather Service, the Owner



should activate his emergency operation and warning system procedures.

(4) Schedule more frequent visits to observe the condition of the dam.


Submitted by:

GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.

*A. C. Hooke*

A. C. HOOKE  
Head, Dam Section

Date: 30 April 1979



Approved by:

DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT, CORPS OF ENGINEERS

LAKE HENRY DAM



Overview

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY

PENNSYLVANIA

LAKE HENRY DAM

NDI ID No. PA-00366  
DER ID No. 35-16  
PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

SECTION 1

PROJECT INFORMATION

1.1 General.

a. Authority. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. Purpose. The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Lake Henry Dam consists of two homogeneous earthfill embankments with masonry core-walls. The embankments are separated by natural ground, the top of which is lower than the top of the embankments. The spillway and outlet works are located in the right embankment. The right embankment is 1,125 feet long and 12 feet high at maximum section. This embankment curves around the lake. The left embankment is 648 feet long and 7 feet high at maximum section. The embankments are separated by a 260-foot length of natural ground, the lowest point of which is 1.8 feet below the design top elevation of the embankments.

The masonry gravity spillway is located at about the center of the right embankment. The crest is 27.2 feet long and it is 2.5 feet below the design top elevation of the dam. The outlet works is about 100 feet to the left of the spillway. It consists of a dry masonry intake structure, a 24-inch diameter cast-iron pipe, and a dry masonry valve pit at the downstream toe of the right embankment. The pipe discharges directly into the stream about 150 feet downstream from the embankment.

b. Location. The dam is located on Lake Run approximately 3.9 miles southeast of Moscow, Pennsylvania. Lake Henry Dam is shown on USGS Quadrangle, Sterling, Pennsylvania, with coordinates N41°17'05" - W75°29'20", in Lackawanna County, Pennsylvania. The dam is 1.9 miles upstream from Hollister Dam, which is breached, and 6.4 miles upstream from Elmhurst Dam. Both Hollister Dam and Elmhurst Dam are on Roaring Brook. The confluence of Lake Run and Roaring Brook is just upstream from Hollister Dam. The location map is shown on Plate 1.

c. Size Classification. Small (12 feet high, 811 acre-feet).

d. Hazard Classification. High hazard. Downstream conditions indicate that a high hazard classification is warranted for Lake Henry Dam (Paragraph 5.1c.).

e. Ownership. Pennsylvania Gas and Water Company, Wilkes-Barre, Pennsylvania.

f. Purpose of Dam. Water supply for Scranton and Dunmore, Pennsylvania.

g. Design and Construction History. Lake Henry was originally a natural lake. Water rights to the lake were acquired by the Owner, under another name, in 1872. Apparently the original Lake Henry Dam was built some years later. In 1895, the two embankments were raised 6.5 feet. The masonry core-walls were apparently built at this time. The raising was apparently designed by William Marple, the Owner's Chief Engineer. The earliest drawings of the dam are dated 1914, when the dam was surveyed at the request of the Pennsylvania Water Supply Commission for their report on the dam. At some later time, the outlet works valve was moved from near the outfall to the downstream toe of the embankment.

1.3 Pertinent Data.

|    |   |         |
|----|---|---------|
| a. | <u>Drainage Area.</u> (square miles.)                   | 0.3     |
| b. | <u>Discharge at Damsite.</u> (cfs.)                     |         |
|    | Maximum known flood at damsite                          | unknown |
|    | Outlet Works at maximum pool elevation<br>(Approximate) | 50      |
|    | Spillway capacity at maximum pool<br>elevation          |         |
|    | Design Conditions:                                      |         |
|    | Spillway  | 333     |
|    | Low area between embankments                            | 379     |
|    | Total   | 712     |
|    | Existing conditions:                                    |         |
|    | Spillway  | 204     |
|    | Low area between<br>embankments                         | 86      |
|    | Total   | 290     |
| c. | <u>Elevation.</u> (feet above msl.)                     |         |
|    | Top of dam (design)                                     | 1908.3  |
|    | Top of dam (existing)                                   | 1907.6  |
|    | Maximum pool  | 1907.6  |
|    | Normal pool   | 1905.8  |
|    | Natural Lake (approximate)                              | 1891.4  |
|    | Upstream invert outlet works                            | 1891.4  |
|    | Downstream invert outlet works                          | 1889.7  |
|    | Streambed at toe of dam<br>(approximate)                | 1896.0  |
| d. | <u>Reservoir Length.</u> (miles.)                       |         |
|    | Normal pool   | 0.5     |
|    | Maximum pool  | 0.5     |
| e. | <u>Storage</u> (acre-feet.)                             |         |
|    | Natural Lake (approximate)                              | 65      |
|    | Normal pool   | 629     |
|    | Maximum pool (design)                                   | 811     |
| f. | <u>Reservoir Surface</u> (acres.)                       |         |
|    | Natural Lake (approximate)                              | 15.4    |
|    | Normal pool   | 69.4    |
|    | Maximum pool (design)                                   | 76.3    |

g. Dam.

|                                |  |
|--------------------------------|--|
| <u>Type</u> (both embankments) | Homogeneous<br>earthfill with<br>masonry<br>core-wall. |
|--------------------------------|--|

Length (feet)

|                  |       |
|------------------|-------|
| Right Embankment | 1,125 |
| Left Embankment  | 648   |

Height (feet)

|                  |    |
|------------------|----|
| Right Embankment | 12 |
| Left Embankment  | 7  |

Topwidth (feet)

|                  |                   |
|------------------|-------------------|
| Right Embankment | Varies,           |
| Left Embankment  | 7 is typical<br>4 |

Side Slopes

|                              |                                     |
|------------------------------|-------------------------------------|
| Right Embankment             |                                     |
| Upstream below<br>El. 1905.8 | Varies<br>1V on 3.5H<br>to 1V on 5H |
| Upstream above<br>El. 1905.8 | Near<br>vertical                    |
| Downstream                   | Varies<br>1V on 2H to<br>1V on 3H   |

|                              |            |
|------------------------------|------------|
| Left Embankment              |            |
| Upstream below<br>El. 1905.8 | 1V on 5H   |
| Upstream above<br>El. 1905.8 | 1V on 1H   |
| Downstream                   | 1V on 2.5H |

Zoning (both embankments)

None

Cutoff (both embankments)

Core-wall

Grout Curtain

None

|    |   |  |
|----|---|--|
| h. | <u>Diversion and Regulating Tunnel.</u> | None   |
| i. | <u>Spillway.</u>                        |  |
|    | <u>Type</u>                             | Masonry gravity weir with inclined top                                     |
|    | <u>Length of Weir. (feet).</u>          | 27.2   |
|    | <u>Crest Elevation</u>                  | 1905.8   |
|    | <u>Upstream Channel</u>                 | Reservoir  |
|    | <u>Downstream Channel</u>               | Apron 3.8 feet below weir crest. It extends beyond the embankment          |
|    | <u>Low Area Between Embankments</u>     | See Text   |
| j. | <u>Regulating Outlets.</u>              |  |
|    | <u>Type</u>                             | Cast-iron pipe, 24-inch diameter   |
|    | <u>Length (feet.)</u>                   | 200  |
|    | <u>Closure</u>                          | 24-inch gate valve in valve pit immediately downstream of right embankment |
|    | <u>Access</u>                           | From right embankment  |

## SECTION 2

### ENGINEERING DATA

#### 2.1 Design.

a. Data Available. Very little engineering data were available for review. In a study performed in 1914 by the Pennsylvania Water Supply Commission, an account of design concepts, geology, construction materials and methods, and design features was prepared from interviews with the Owner, visual inspection, and other sources. The 1914 study also included analyses for hydrology and hydraulics. A summary of the results of the analyses is on file.

b. Design Features. The dam and appurtenances are described in Paragraph 1.2a. The design features are shown on the Plates at the end of the report and on the Photographs in Appendix D. Plate 2 shows a plan of the dam. The right embankment is shown on Photograph A. The left embankment is shown on Photograph C. A profile of the embankments is shown on Plate 4. Typical sections of the embankments are shown on Plate 3. The spillway is shown on Plate 3 and Photographs E and F. The outlet works is shown on Plate 5 and Photograph B.

There is conflicting data between Plates 2 and 3 and Plates 4 and 5. All are somewhat in conflict with the information gathered during the survey performed for this inspection, as shown in Appendix B. This will be discussed in Sections 5 and 6.

Plates 2 and 3 are dated 1914. It is believed that Plates 4 and 5 were prepared after that date. No design drawings are available.

c. Design Considerations. Almost nothing is known about the design of the dam.

#### 2.2 Construction.

a. Data Available. Construction data available for review for the original structures were limited to information contained in the 1914 Report prepared by the Pennsylvania Water Supply Commission. That information was obtained by interviews with the Owner, and it gives very scant details of the construction operations. The report states that it was impossible to obtain reliable information concerning the construction



of the dam. According to the report, the caretaker stated that the masonry core-wall was founded on a stratified sandstone. No other construction information was cited in the report.

b. Construction Considerations. Since the available information is limited, construction methods cannot be assessed.

2.3 Operation. There are no formal records of operation. Based on information from the Owner and the caretaker of the dam, all structures have performed satisfactorily.

#### 2.4 Evaluation.

a. Availability. Engineering data was provided by the Bureau of Dam Safety, Obstructions, and Storm Water Management, Department of Environmental Resources, Commonwealth of Pennsylvania (PennDER), and by the Owner, Pennsylvania Gas and Water Company. The Owner made available a senior construction supervisor for information during the visual inspection. The Owner also researched his files for additional information upon request of the inspection team.

b. Adequacy. The type and amount of design data and other engineering data is very limited, and the assessment must be based on the combination of available data, visual inspection, performance history, hydrologic assumptions, and hydraulic assumptions.

c. Validity. There is no reason to question the validity of the available data. As noted previously, there is conflicting data, which is discussed hereafter.

SECTION 3  
VISUAL INSPECTION

3.1 Findings

a. General. The overall appearance of the dam is fair, with some deficiencies as noted herein. The locations of deficiencies are shown in Appendix B on Plate B-1. Survey data acquired during this inspection is presented in Appendix B. On the day of the inspection, the pool was 5.8 feet below the spillway crest.

b. Embankments. Both embankments are thickly covered by ferns. The caretaker of the dam reported that this was a normal summer's growth. The brush had been cut the previous spring. Trees are growing at the toes of both embankments. The riprap on both embankments only extends up to the spillway crest. The riprap is in good condition. The tops of both embankments have low areas. The low areas extend over most of the tops of both embankments. The lowest point on the right embankment is 0.7 foot below the design top elevation; the lowest point on the left embankment is 0.6 foot below the design top elevation. The existing profiles are shown in Appendix B.

The profile of the natural ground between the embankments is shown in Appendix B. There is a hole, about 3 feet deep and 5 feet in diameter at the right abutment of the left embankment. The hole appeared similar to those left by trees when they are uprooted. No conditions as to what caused the hole were evident.

c. Appurtenant Structures. The outlet works is in good condition. On the day of the inspection, the outlet works valve was operated with no observed deficiencies. The outlet works pipe extends under pressure through the embankment. Clear seepage of 0.5 gpm was observed flowing from under the end of the pipe.

The masonry spillway is in fair condition. The mortar in the spillway walls is somewhat deteriorated. Thick brush is growing in the spillway apron. The stumps remaining from brush cutting are pushing up the paving in areas of the apron.

d. Reservoir Area. The reservoir has generally gentle slopes. The watershed is mostly uninhabited and undeveloped. Some of it is owned and controlled by Pennsylvania Gas and Water Company. There is minor suburban development on the hill by the right abutment of the right embankment.

e. Downstream Channel. The natural channel proceeds for about 1.4 miles through an uninhabited reach to Hollister Reservoir. Hollister Dam belongs to Pennsylvania Gas and Water Company. It is breached. The stream then extends a short distance to a culvert under a railroad embankment. The stream then flows for 2.1 miles to Moscow, which has homes directly adjacent to the low river banks. The stream then flows for 1.4 miles into Elmhurst Reservoir. The access road to the dam extends through a swamp to the left of the dam. On the day of the inspection, it was barely passable by a high ground clearance vehicle.

## SECTION 4

### OPERATIONAL PROCEDURES

4.1 Procedure. The reservoir is maintained at spillway crest, Elevation 1905.8, with excess inflow discharging over the spillway and into Lake Run, which eventually flows into Elmhurst Reservoir about 5 miles downstream. A 24-inch diameter cast-iron pipe discharges water from the reservoir. Streamflows in Lake Run can be increased by releases from Lake Henry Dam. Since streamflow is usually augmented only when Elmhurst Reservoir is below spillway crest elevation, the valve on the Lake Henry water discharge line is usually closed.

The Owner, while responsible for the dam, does not have water rights for the entire storage. He can only utilize the upper portion of the stored water.

4.2 Maintenance of Dam. The dam is visited monthly, except during the winter, by a caretaker who records the reservoir elevation. The dam is not visited during the winter. Reports are mailed to the Owner's Engineering Department. This information is used by the Owner's Engineering Department for regulating flows in the distribution system. The caretaker is also responsible for observing the general condition of the dam and appurtenant structures and for reporting any changes or deficiencies to the Owner's Engineering Department. A Pennsylvania Gas and Water Company engineer makes a formal inspection of the dam each year, and the records are filed and used for determining the priority of repairs. Informal inspections are also made when the engineer is on the site for other reasons. Brush on the embankments is cut annually.

4.3 Maintenance of Operating Facilities. The valve on the outlet works pipe is operated infrequently. In response to the Phase I Dam Inspection Program of the previous year, the Owner is revising his maintenance procedures. Details of the procedures are still being developed.

4.4 Warning Systems in Effect. The Owner furnished the inspection team with a verbal description of the chain of command for Lake Henry Dam and of a generalized emergency notification list that is applicable for all of the Pennsylvania Gas and Water Company dams. The Owner said that during periods of heavy rainfall,

available personnel are dispatched to the dams to observe conditions. All company vehicles are equipped with radios, and the personnel can communicate with each other and with a central control facility. Evaluation of risk is made by the Owner's Engineering Department. The Owner's Engineering Department is also responsible for notification of emergency conditions to the local authorities. Detailed emergency operational procedures have not been formally established for Lake Henry Dam, but are as directed by the Owner's Engineering Department.

4.5 Evaluation of Operational Adequacy. Maintenance of the dam, except for the brush in the spillway outlet channel, appears good. Although the outlet works valve operated adequately, the maintenance procedures for the valve could be improved. More frequent visits to observe the conditions at the dam, especially in the winters, appear to be warranted. The procedures used by the Owner for inspecting the dam are adequate, but some needed repairs have not been made. In general, the warning system is adequate, but it would be more effective if it were more detailed.

## SECTION 5

### HYDROLOGY AND HYDRAULICS

#### 5.1 Evaluation of Features.

a. Design Data. In their 1914 Report, the Pennsylvania Water Supply Commission estimated the design spillway capacity at 225 cfs. This was estimated using a 1.9 foot maximum head. It was also estimated using a 28.3-foot crest length, as discussed hereafter. A design spillway capacity of 333 cfs is used for this study (Appendix C). Additional spillway capacity is available at the low area that separates the embankments, as is discussed hereafter.

b. Experience Data. The Owner did not report any hydraulic problems with the dam. He does not have any information concerning flows during times of flood.

#### c. Visual Observations.

(1) General. The visual inspection of Lake Henry Dam, which is described in Section 3, resulted in a number of observations relevant to hydraulics and hydrology. These observations are evaluated herein for the various features.

(2) Embankments. The low areas at the top of the embankments reduce the spillway discharge capacity. The low area of natural ground between the embankments will convey outflow before the embankments are overtopped. This may cause some erosion at the abutments of the embankments, and it is considered an erosion hazard. However, it is not felt that it would cause failure of the dam. Since the area acts as an auxiliary spillway, grading the area, clearing it of the minor amount of brush present, and protecting the ends of the embankments would appear to be warranted.

There is some concern that this condition was never officially reported during the previous inspections by the Commonwealth. The condition was very noticeable on the day of the inspection.

(3) Appurtenant Structures. Except for the pipe extending under pressure through the embankment, no deficiencies were observed at the outlet works. The Owner stated that various size plugs and an in-house diving capability are available to provide

upstream closure. This is deemed adequate, if the correct size plug is readily available.

The brush in the spillway apron will raise tailwater. It is estimated that this will not reduce the spillway discharge capacity. However, it provides a greater erosion potential at the embankment. The stumps, which push-up the apron paving, are creating an erosion hazard. Previous reports, as well as Plate 3, indicate that the spillway crest length is 28.3 feet. A crest length of 27.2 feet was measured for this inspection and is used in this study. The reasons for the variation are unknown.

(4) Reservoir Area. No conditions were observed in the reservoir area or watershed that might present significant hazard to the dam. The records state that the drainage area at the site is 0.9 square mile. This estimate was from 1914, or earlier, and never updated. Using more recent USGS mapping, the drainage area measures to be 0.3 square mile, which is used in this study. The assessment of the dam is based on existing conditions, and the effects of future development are not considered.

(5) Downstream Conditions. No conditions were observed immediately downstream from the dam that would create significant hazard to the dam. If the dam should fail, a hazard to at least 12 dwellings in Moscow would exist. Hollister Dam and the railroad culvert immediately downstream of it could provide significant mitigating effects to floodflows from Lake Henry Dam. In addition, the floodflows would discharge into Elmhurst Reservoir. A Phase I Inspection Report for the National Dam Inspection Program has previously been prepared for Elmhurst Dam, which is of intermediate size. Elmhurst Dam was classified as high hazard, with an inadequate spillway. It is not felt that the failure of Lake Henry Dam would pose a significant threat to Elmhurst Dam. Because of the possibility of flooding dwellings in Moscow, a high hazard classification is warranted for Lake Henry Dam. Access to Lake Henry Dam is poor. There is an alternate access route to the dam through the development near the right abutment of the right embankment. The Owner does not use this route, the last 300 feet of which is not traversable by vehicle.

d. Overtopping Potential.

(1) Spillway Design Flood. According to the criteria established by the Office of the Chief

of Engineers (OCE) for the size (Small) and hazard potential (High) of Lake Henry Dam, the spillway design flood (SDF) varies between the probable maximum flood (PMF) and the 1/2 PMF. The PMF is selected as the SDF because of the number of dwellings that could be flooded in Moscow.

(2) Description of Model. The watershed was modeled with the HEC-1DB computer program. The HEC-1DB computer program computes a PMF runoff hydrograph and routes the flows through both reservoirs and stream sections. In addition, it has the capability to simulate an overtopping dam failure. The PMF inflow to Lake Henry was determined and routed through the dam. Identical methods were used for various percentages of the PMF.

(3) Summary of Results. Pertinent results are tabularized at the end of Appendix C. The analysis reveals that Lake Henry Dam, with its existing top elevation of 1907.6 can pass approximately 60 percent of the PMF without overtopping.

If Lake Henry Dam were raised to its design elevation of 1908.3, it would be able to pass the PMF with 0.05 foot of freeboard remaining.

(4) Spillway Adequacy. The criteria used to rate the spillway adequacy of a dam are described in Appendix C. Since Lake Henry Dam cannot pass the PMF but can pass the 1/2 PMF, the spillway capacity is rated as inadequate. If the dam were raised to its design elevation, the spillway would be rated as adequate.



## SECTION 6

### STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability.

##### a. Visual Observations.

(1) General. The visual inspection of Lake Henry Dam, which is described in Section 3, resulted in a number of observations relevant to structural stability. These observations are evaluated herein for various features.

(2) Embankments. The brush on the embankments is sufficiently small that it presents no hazard to the embankment. It did hinder the visual inspection. Trees at the toes of the slopes are undesirable. The riprap not extending to top of dam is an erosion hazard.

Reference is made to Plates 3 and 5, and the cross-sections in Appendix B. The cross-sections show conflicting slopes. The reason for this is unknown. The slopes listed in the pertinent data were taken from Appendix B. The design top elevation of the dam is taken from Plate 3. The height of the right embankment is taken from Plate 5. There is no concern about the existing slopes of the embankment except for the upper 2 feet of the upstream slope, which is 1V on 1H at the flattest and near-vertical at places. As noted above, this slope is unprotected.

The low areas at the tops of the embankments are probably caused by settlement. Low areas were noted in some of the periodic inspections by the Commonwealth. The low area between the embankments is evaluated in Section 5.

The cause of the hole at the right end of the left embankment is unknown. There is no evidence of conditions hazardous to the dam. However, it could be an indication of more serious problems.

Observations concerning seepage through the embankment were not definitive because of the low pool on the day of inspection. No seepage or wet areas were observed near the embankment on the day of the inspection.

(3) Appurtenant Structures. The end of the outlet works pipe is 150 feet downstream from the embankment. The seepage observed at the end of the pipe is not excessive. It could be caused by either the natural ground water levels or by a leak in the pipe joints. Because the pool was low, the observed seepage was probably lower than that which would occur during normal pool conditions.

The deteriorated mortar in the spillway is an indication of the lack of maintenance.

b. Design and Construction Data. There is no stability analysis for the embankment. There is no evidence of significant problems that presently threaten the embankment. It is judged that the spillway section that is shown on Plate 3 should be stable under the maximum loading condition. Stability analysis is not usually performed on a structure of this height.

c. Operating Records. There are no formal records of operation. According to the Owner, no stability problems have occurred over the operational history of the dam.

d. Postconstruction Changes. As noted herein, there is sufficient information available on all modifications made to Lake Henry Dam, such that its stability can be assessed.

e. Seismic Stability. Lake Henry Dam is located in Seismic Zone 1. Normally it can be considered that if a dam in this zone has adequate factors of safety under static loading conditions, it can be assumed safe for any expected earthquake loading. However, since there are no formal stability analyses and since there is the possibility of earthquake forces cracking the masonry core-wall, the theoretical seismic stability of Lake Henry Dam is not known.

SECTION 7  
ASSESSMENT, RECOMMENDATIONS, AND  
PROPOSED REMEDIAL MEASURES.

7.1 Dam Assessment.

a. Safety.

(1) Based on visual inspection, available records, calculations, and past operational performance, Lake Henry Dam is judged to be in good condition. With existing conditions, the spillway can pass 60 percent of the PMF without overtopping of the dam. The spillway capacity is rated as inadequate. If the Dam were raised to its design elevation, it could pass the PMF with 0.05 foot of freeboard. The spillway capacity would then be rated as adequate. A low area between the embankments acts as an auxiliary spillway.

(2) There is no stability analysis for the embankment. There is no evidence of significant problems threatening the embankment. The spillway weir is judged to be stable.

(3) The visual inspection revealed some deficiencies, which are summarized below for the various features.

| <u>Feature and Location</u>  | <u>Observed Deficiencies</u>                                 |
|------------------------------|--|
| <u>Embankments:</u>          |  |
| Toes                         | Trees  |
| Upstream slope               | Steep upper slope<br>without riprap                          |
| Right end of left embankment | Hole   |
| Top                          | Low areas  |
| <u>Spillway:</u>             |  |
| Walls                        | Deteriorated mortar  |
| Apron                        | Brush, dislodged paving                                      |
| <u>Outlet Works:</u>         |  |
|                              | Uncertain upstream<br>closure facilities,<br>seepage at end. |

Feature and Location

Observed Deficiencies

Access:

Access road in poor condition.

b. Adequacy of Information. The information available is such that an assessment of the condition of the dam can be inferred from the combination of visual inspection, past performance, and computations performed prior to and as part of this study.

c. Urgency. The recommendations in Paragraph 7.2 should be implemented without delay.

d. Necessity for Further Investigations. Accomplishment of the remedial measures outlined in Paragraph 7.2, do not require further investigations by the Owner.

7.2 Recommendations and Remedial Measures.

a. The following measures are recommended to be undertaken by the Owner, in approximate order of priority, as soon as practical:

(1) Raise the embankments to their design elevation.

(2) Extend the riprap on the upstream embankment slopes to the top of the dam. This should be accomplished in a manner to acceptably flatten the upstream slopes.

(3) Grade the low area between the embankments to provide better hydraulic control. Provide erosion protection at the abutments of both embankments.

(4) Fill the hole at the end of the left embankment. Continue to observe the area. If changes are noted, take immediate remedial action.

(5) Remove the brush in the spillway channel and the trees at the toes of the embankment slopes.

(6) Repair the mortar in the spillway walls and the paving in the spillway apron.

(7) Monitor the seepage at the end of the outlet works pipe. The embankment should be inspected for seepage with the pool at spillway crest level. If changes are noted, take appropriate action.

(8) Ensure that a proper size plug is available to provide upstream closure at the outlet works.

(9) Determine if adequate access is available from the right abutment of the right embankment. If it is not, improve the access road.

b. In addition, it is recommended that the Owner modify his operational procedures as follows:

(1) Develop a detailed emergency operation and warning system for Lake Henry Dam.

(2) Provide round-the-clock surveillance of Lake Henry Dam during periods of unusually heavy rains.

(3) When warnings of a storm of major proportions are given by the National Weather Service, the Owner should activate his emergency operation and warning system procedures.

(4) Schedule more frequent visits to observe the condition of the dam.

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY  
PENNSYLVANIA

LAKE HENRY DAM


NDI ID No. PA-00366  
DER ID No. 35-16

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

APRIL 1979


PLATES



ROARING BROOK

HOLLISTER DAM  
(BREACHED)

MOSCOW



LAKE RUN

RIGHT EMBANKMENT

LAKE HENRY


LEFT EMBANKMENT

2000 0 2000  
SCALE: 1 IN. = 2000 FT.

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
  
LAKE HENRY DAM  
PENNSYLVANIA GAS AND WATER COMPANY  
  
LOCATION MAP  
  
APRIL 1979 PLATE 1

2






LAKE H  
Capacity 204,920  
Area Flooded 6940  
Area of Flood 11

MAP  
Showing  
LAKE HENRY DAM & RESERVOIR  
in  
Covington Twp. Lackawanna Co.  
THE SCRANTON GAS & WATER CO.  
March 14 1914  
Scale 1" = 100'  
R. L. Fairbank  
Chief Engineer

SHEET 1



LAKE HENRY.  
204.926, 986 Gals  
d 6940 Acres  
and 0.154 N.I.

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM


LAKE HENRY DAM  
PENNSYLVANIA GAS AND WATER COMPANY

PLAN


APRIL 1979

2

PLATE 2



PLAN OF SPILLWAY  
Scale 1"=4'




SECTION A-B.  
Through Spillway  
Scale 1"=4'

THIS PAGE IS BEST QUALITY PRACTICE DRAWING  
FROM COPY FURNISHED TO DDC

| Point | Elevation | Notes |
|-------|-----------|-------|
| 3.5   | 48.50     |       |
| 9.5   | 21.04     |       |
| 9.1   | 21.07     |       |
| 108   | 5.15      |       |
| 110   | 55.103    |       |
| 111   | 19        |       |
| 114   | 19 71     |       |
| 115   | 1- 13     |       |
| 191   | 107       |       |

FROM COPY FURNISHED TO DDO



PHASE I INSPECTION  
NATIONAL DAM INSPECTION  
LAKE HENRY DAM  
PENNSYLVANIA GAS AND WATER  
TYPICAL SECTION  
APRIL 1979

9'



10

NO WATER COLLECTED

## SECTION.

**FULLY**

S. G. & W. G.  
Supply Dam  
Sheet 15



## ELEVATIONS OF 2-DMS

Scales: Vert: 1" = 20'  
Horiz: 1" = 200'

THIS PAGE IS BEST QUALITY REPRODUCTION  
FROM COPY 213 - 1000 TO DDC


PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

LAKE HENRY DAM  
PENNSYLVANIA GAS AND WATER COMPANY

PROFILES

APRIL 1979

PLATE 4



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

LAKE HENRY DAM  
PENNSYLVANIA GAS AND WATER COMPANY

OUTLET WORKS

APRIL 1979

PLATE 5

1. The structure  
is in good condition  
and is in good  
condition.

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY  
PENNSYLVANIA

LAKE HENRY DAM

NDI ID No. PA-00366  
DER ID No. 35-16

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

APRIL 1979

APPENDIX A  
CHECKLIST - ENGINEERING DATA



# CHECKLIST

## ENGINEERING DATA

### DESIGN, CONSTRUCTION, AND OPERATION PHASE I

NAME OF DAM: LAKE HENRY  
 I PA-00366  
 ND ID NO.: 35-16

Sheet 1 of 4

| ITEM  | REMARKS  |
|---|--|
| AS-BUILT DRAWINGS   | SEE PLATES 2-5<br>NOT "AS-BUILT" - PREPARED FOR 1914<br>REPORT AND MODIFICATIONS |
| REGIONAL VICINITY MAP   | SEE PLATE 1  |
| CONSTRUCTION HISTORY  | BUILT AT UNCERTAIN DATE<br>RAISED IN 1895 OR 1896                                |
| TYPICAL SECTIONS OF DAM   | SEE PLATE 3  |
| OUTLETS:<br>Plan<br>Details<br>Constraints<br>Discharge Ratings | SEE PLATE 2  |

## ENGINEERING DATA

Sheet 2 of 4

| ITEM   | REMARKS   |
|--|---|
| RAINFALL/RESERVOIR RECORDS   | NONE  |
| DESIGN REPORTS   | NONE  |
| GEOLOGY REPORTS  | 1914 PENNSYLVANIA WATER SUPPLY COMMISSION<br>REPORT                                     |
| DESIGN COMPUTATIONS:<br>Hydrology and Hydraulics<br>Dam Stability<br>Seepage Studies | IN 1914 REPORT BY PENNSYLVANIA<br>WATER SUPPLY COMMISSION -<br>HYDRAULICS AND HYDROLOGY |
| MATERIALS INVESTIGATIONS:<br>Boring Records<br>Laboratory<br>Field                   | NONE  |
| POSTCONSTRUCTION SURVEYS OF DAM  | SEE PLATES 2-5  |

## ENGINEERING DATA

Sheet 3 of 4

| ITEM   | REMARKS                  |
|--|--------------------------|
| BORROW SOURCES   | NOT AVAILABLE            |
| MONITORING SYSTEMS   | NONE                     |
| MODIFICATIONS  | SEE CONSTRUCTION HISTORY |
| HIGH POOL RECORDS  | NONE                     |
| POSTCONSTRUCTION ENGINEERING STUDIES AND REPORTS             | NONE                     |
| PRIOR ACCIDENTS OR FAILURE OF DAM:<br>Description<br>Reports | NONE                     |

## ENGINEERING DATA

Sheet 4 of 4

| ITEM  | REMARKS   |
|---|---|
| MAINTENANCE AND OPERATION RECORDS             | NOT AVAILABLE   |
| SPILLWAY:<br>Plan<br>Sections<br>Details      | SEE PLATE 3   |
| OPERATING EQUIPMENT:<br>Plans<br>Details      | SEE PLATE 2   |
| PREVIOUS INSPECTIONS<br>Dates<br>Deficiencies | <p>1920 - TOP OF DAM LOW AND UNEVEN, ESPECIALLY TO THE RIGHT OF THE SPILLWAY. THE SPILLWAY NEEDS POINTING AND BRUSH IS GROWING IN IT. BRUSH AND TREES ON THE EMBANKMENT. ORDERED REPAIRED PER 1914 REPORT.</p> <p>1921 - PER 1920 AND ALSO MASONRY AT OUTLET COLLAPSED. REPAIRS ORDERED.</p> <p>1921 - ALL ITEMS ABOVE REPAIRED EXCEPT BRUSH CUT NOT COMPLETE.</p> <p>1924 - GROUND SEPARATING EMBANKMENTS IS LOWER THAN TOP OF EMBANKMENTS. SEE PAGE TO RIGHT OF SPILLWAY.</p> |

A-4

THIS REPORT WAS PREPARED FROM DATA FURNISHED TO DOD

## ENGINEERING DATA

Sheet 4a of 4

| ITEM                                | REMARKS  |
|-------------------------------------|--|
| PREVIOUS INSPECTIONS<br>(CONTINUED) | 1928- GROUND DOWNSTREAM OF EMBANKMENT TO RIGHT OF EMBANKMENT IS SWAMPY.<br>1932- GROUND DOWNSTREAM OF TOE IS SWAMPY. LEFT EMBANKMENT IS COVERED WITH BRUSH.                      |
|                                     | 1937- Top of dam is uneven, downstream toe is swampy in spots to the left of the spillway and continuously swampy to the right.  |
|                                     | 1941- Top of dam is uneven. "JOINTS HAVE STARTED TO OPEN IN THE MASONRY AT DOWNSIDE: FACE OF SPILLWAY SECTION." SLIGHT SEEPAGE AT LOWER END OF BLOWOFF; TOE TO RIGHT OF SPILLWAY |
|                                     | IS SWAMPY. "JOINTS OF MASONRY HAVE STARTED TO OPEN IN SPILLWAY ABUTMENT WALLS." BRUSH IN SPILLWAY CHANNEL<br>1945 - PER 1941.<br>1953 - Top of dam is slightly uneven.           |
|                                     | SPILLWAY ABUTMENTS NEED REPOINTING. SMALL AMOUNT OF SEEPAGE ALONG RIGHT TOE. BRUSH ON EMBANKMENT.  |
|                                     |  |

A-5

THIS PAGE IS BEST QUALITY REPRODUCTION  
FROM COPY FURNISHED TO DDC

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY

PENNSYLVANIA

LAKE HENRY DAM

NDI ID No. PA-00366  
DER ID No. 35-16

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

APRIL 1979

APPENDIX B

CHECKLIST - VISUAL INSPECTION

# CHECKLIST

## VISUAL INSPECTION

### PHASE I

Name of Dam: LAKE HENRY County: LACKAWANNA State: PENNSYLVANIA  
 NDS ID No.: PA-00366 DER ID No.: 35-16  
 Type of Dam: EARTH FILL w/ MASONRY CORE-WALL Hazard Category: HIGH  
 Date(s) Inspection: OCTOBER 27, 1978 Weather: CLOUDY Temperature: 55°F  
 Soil Conditions: VERY MOIST

0-1

Pool Elevation at Time of Inspection: 1900.0 msl/Tailwater at Time of Inspection: NONE msl

#### Inspection Personnel:

D. WOLF (GFCC) R. GLOCKNER (PGW)  
D. EBERSOLE (GFCC)  
J. BORDNAR (PGW)

A. WHITMAN (GFCC) Recorder

# EMBANKMENT

Sheet 1 of 2

| VISUAL EXAMINATION OF   | RIGHT EMBANKMENT<br>OBSERVATIONS                    | LEFT EMBANKMENT<br><del>REMARKS OR RECOMMENDATIONS</del>                   |
|---|---|--|
| SURFACE CRACKS  | NONE  | NONE   |
| UNUSUAL MOVEMENT OR<br>CRACKING AT OR BEYOND<br>THE TOE       | NONE  | HOLE TO RIGHT<br>OF LEFT EMBANKMENT  |
| SLOUGHING OR EROSION:<br>Embankment Slopes<br>Abutment Slopes | NONE  | NONE   |
| CREST ALIGNMENT:<br>Vertical<br>Horizontal                    | SEE SURVEY DATA<br>FOLLOWING INSPECTION<br>FORMS.   | SEE RIGHT EMBANKMENT   |
| RIPRAP FAILURES   | SEE SURVEY DATA<br>RIPRAP DOES NOT<br>EXTEND TO THE | TOP OF THE DAM<br>ON BOTH EMBANKMENTS.<br>OTHERWISE, IN GOOD<br>CONDITION. |



# EMBANKMENT

Sheet 2 of 2

| VISUAL EXAMINATION OF   | RIGHT EMBANKMENT<br>OBSERVATIONS  | LEFT EMBANKMENT<br>REMARKS OR RECOMMENDATIONS       |
|---|---|---|
| JUNCTION OF EMBANKMENT<br>WITH:<br>Abutment<br>Spillway<br>Other Features | ARE IT SEPARATING<br>THE EMBANKMENTS<br>IS LOW, SEE<br>SURVEY DATA.               | SEE RIGHT<br>EMBANKMENT.                            |
| ANY NOTICEABLE SEEPAGE  | NONE  | NONE  |
| STAFF GAGE AND RECORDER   | NONE  | NONE  |
| DRAINS  | NONE  | NONE  |
| BRUSH   | 2' HIGH FERNS COVER<br>THE TOP AND DOWN-<br>STREAM SLOPES OF<br>BOTH EMBANKMENTS. | TREES ARE GROWING<br>ALONG BOTH DOWNSTREAM<br>TOES. |

# OUTLET WORKS

Sheet 1 of 1

| VISUAL EXAMINATION OF  | OBSERVATIONS                                     | REMARKS OR RECOMMENDATIONS  |
|--|--|---|
| CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT | 24" CIP<br>NO OBSERVED DEFICIENCIES              |   |
| INTAKE STRUCTURE   | DAY MASONRY -<br>SOMEWHAT IRREGULAR<br>IN SHAPE. | NO DEFICIENCIES.  |
| OUTLET STRUCTURE   | PIPE OUTLETS<br>DIRECTLY TO<br>STREAM.           | SEEPAGE OF 0.5 gpm<br>AT OUTLET, WHICH IS<br>150 FEET FROM EMBANKMENT |
| OUTLET CHANNEL   | NO DEFICIENCIES                                  |   |
| EMERGENCY GATE   | OPERATED WITH<br>NO DIFFICULTY.                  |   |

# UNGATED SPILLWAY

Sheet 1 of 1

| VISUAL EXAMINATION OF               | OBSERVATIONS   | REMARKS OR RECOMMENDATIONS                   |
|-------------------------------------|--|--|
| MASONRY<br><del>CONCRETE</del> WEIR | WEIR IS COVERED<br>WITH CONCRETE. NO<br>DEFICIENCY.            |  |
| APPROACH CHANNEL                    | RESERVOIR  |  |
| DISCHARGE CHANNEL                   | THICK BRUSH IN<br>APRON AREA; STUMPS ARE<br>PUSHING UP PAVING. | MORTAR IN WALLS<br>IS SOMEWHAT DETERIORATED. |
| BRIDGE AND PIERS                    | N/A  |  |
|                                     |  |  |

# INSTRUMENTATION

Sheet 1 of 1

| VISUAL EXAMINATION OF | OBSERVATIONS | REMARKS OR RECOMMENDATIONS |
|-----------------------|--------------|----------------------------|
| MONUMENTATION/SURVEYS | NONE         |                            |
| OBSERVATION WELLS     | NONE         |                            |
| WEIRS                 | NONE         |                            |
| PIEZOMETERS           | NONE         |                            |
| OTHER                 | NONE         |                            |

# RESERVOIR AND WATERSHED

Sheet 1 of 1

| VISUAL EXAMINATION OF | OBSERVATIONS  | REMARKS OR RECOMMENDATIONS |
|-----------------------|---|----------------------------|
| SLOPES                | GENERALLY MILD  |                            |
| SEDIMENTATION         | NO OBSERVED OR<br>REPORTED PROBLEMS.                      |                            |
| WATERSHED DESCRIPTION | WOODED. MINOR<br>SUBURBAN DEVELOPMENT<br>IN A SMALL PART. |                            |
|                       |   |                            |
|                       |   |                            |


# DOWNSTREAM CHANNEL

Sheet 1 of 1

| VISUAL EXAMINATION OF                         | OBSERVATIONS  | REMARKS OR RECOMMENDATIONS                                    |
|---|---|---|
| CONDITION:<br>Obstructions<br>Debris<br>Other | NONE, CHANNEL<br>FLOWS THROUGH A<br>SWAMP                   |   |
| SLOPES  | GENERALLY MILD  |   |
| APPROXIMATE NUMBER OF HOMES AND POPULATION    | TOWN OF MOSCOW,<br>MANY HOMES ON<br>LOW BANKS OF<br>STREAM. | HOLLISTER DAM (BREACHED)<br>BETWEEN MOSCOW<br>AND LAKE HENRY. |
|   |   |   |
|   |   |   |

GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT ELKS CREEK DAM FILE NO. 1852  
Profile - Chain Embankment SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY WFC DATE 12-3-78 CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_




RIGHT EMBANKMENT - PROFILE

B-9

GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.


SUBJECT LAKE HENRY DAM FILE NO. 7052  
SECTION - MAIN EMBANKMENT SHEET NO.        OF        SHEETS  
FOR         
COMPUTED BY DICK DATE 12-8-78 CHECKED BY        DATE       






GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT W.D. HENRY DAM FILE NO. 7832  
PROFILE AUX. EMBANKMENT SHEET NO.      OF      SHEETS  
FOR       
COMPUTED BY JKE DATE 12-11-78 CHECKED BY      DATE     




GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT LAKE HARTLAND FILE NO. 1252  
SECTION - THE EMBANKMENT SHEET NO.      OF      SHEETS  
FOR       
COMPUTED BY DLC DATE 12-11-78 CHECKED BY      DATE     



LEFT EMBANKMENT - SECTION

B-12



NOT TO SCALE

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

LAKE HENRY DAM  
PENNSYLVANIA GAS AND WATER COMPANY  
RESULTS OF VISUAL INSPECTION

APRIL 1979

PLATE B-1

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY  
PENNSYLVANIA

LAKE HENRY DAM

NDI ID No. PA-00366  
DER ID No. 35-16

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

APRIL 1979

APPENDIX C  
HYDROLOGY AND HYDRAULICS

## APPENDIX C

### HYDROLOGY AND HYDRAULICS

In the recommended Guidelines for Safety Inspection of Dams, the Department of the Army, Office of the Chief of Engineers (OCE), established criteria for rating the capacity of spillways. The recommended Spillway Design Flood (SDF) for the size (small, intermediate, or large) and hazard potential (low, significant, or high) classification of a dam is selected in accordance with the criteria. The SDF for those dams in the high hazard category varies between one-half of the Probable Maximum Flood (PMF) and the PMF. If the dam and spillway are not capable of passing the SDF without overtopping failure, the spillway capacity is rated as inadequate. If the dam and spillway are capable of passing one-half of the PMF without overtopping failure, or if the dam is not in the high hazard category, the spillway capacity is not rated as seriously inadequate. A spillway capacity is rated as seriously inadequate if all of the following conditions exist:

(a) There is a high hazard to loss of life from large flows downstream of the dam.

(b) Dam failure resulting from overtopping would significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure.

(c) The dam and spillway are not capable of passing one-half of the PMF without overtopping failure.

# APPENDIX C

SUSQUEHANNA River Basin

Name of Stream: LAKE RUN

Name of Dam: LAKE HENRY

ND<sup>I</sup> ID No.: PA-00366

DER ID No.: 35-16

Latitude: N 41° 17' 05" Longitude: W 75° 29' 20"

Top of Dam <sup>DESIGN</sup> (low spot) Elevation: 1908.3

Streambed Elevation: 1896.0± Height of Dam: 12 ft

Reservoir Storage at Top of Dam Elevation: 811 acre-ft

Size Category: SMALL

Hazard Category: HIGH (see Section 5)

Spillway Design Flood: PMF - BECAUSE HIGHLY POPULATED TOWN OF MOSCON DOWNSTREAM.

## UPSTREAM DAMS

| Name        | Distance from Dam (miles) | Height (ft) | Storage at top of Dam Elevation (acre-ft) | Remarks |
|-------------|---------------------------|-------------|---|---------|
| <u>NONE</u> |                           |             |   |         |
|             |                           |             |   |         |
|             |                           |             |   |         |
|             |                           |             |   |         |

## DOWNSTREAM DAMS

|                       |  |           |             |   |
|-----------------------|--|-----------|-------------|---|
| <u>ELDMURST</u>       |  | <u>64</u> | <u>3744</u> | <u>HIGH HAZARD - SPILLWAY IN ADEQUATE</u> |
| <u>ALSO</u>           |  |           |             | <u>NDI PA-00296</u>                       |
| <u>HOLLISTON</u>      |  |           |             |   |
| <u>DAM - BREACHED</u> |  |           |             |   |

SUSQUEHANNA River Basin

Name of Stream: LAKE RUN

Name of Dam: LAKE HENRY

<sup>I</sup>  
NDS ID No.: PA-00366

DER ID No.: 35-16

Latitude: N 41° 17' 05" Longitude: N 75° 29' 20"

DETERMINATION OF PMF RAINFALL

For Area A

which consists of Subareas A1 of 0.3 sq. mile

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Total Drainage Area 0.3 sq. mile

PMF Rainfall Index = 22.15 in., 24 hr., 200 sq. mile


|                              | Hydromet. 40<br>(Susquehanna Basin) | Hydromet. 33<br>(Other Basins) |
|------------------------------|-------------------------------------|--------------------------------|
| Zone                         | <u>N/A</u>                          | <u>N/A</u>                     |
| Geographic Adjustment Factor | <u>97%</u>                          | <u>1.0</u>                     |
| Revised Index Rainfall       | <u>21.5</u>                         | <u>N/A</u>                     |

RAINFALL DISTRIBUTION (percent)

| <u>Time</u> | <u>Percent</u> |
|-------------|----------------|
| 6 hours     | <u>118</u>     |
| 12 hours    | <u>127</u>     |
| 24 hours    | <u>136</u>     |
| 48 hours    | <u>142</u>     |
| 72 hours    | <u>145</u>     |
| 96 hours    | <u>N/A</u>     |

GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_



NOTE:

AREAS B AND C NOT INCLUDED  
IN COMPUTER ANALYSIS

C-4



Data for Dam at Outlet of Subarea A1  
(see Sketch on Sheet C-4)

Name of Dam: LAKE HENRY Sheet 1 of     

Height: 12 FT (existing)

Spillway Data:

|  | Existing<br>Conditions       | Design<br>Conditions |
|--|------------------------------|----------------------|
| Top of Dam Elevation                   | <u>1907.6</u>                | <u>1908.3</u>        |
| Spillway Crest Elevation               | <u>1905.8</u>                | <u>1905.8</u>        |
| Spillway Head Available (ft)           | <u>1.8</u>                   | <u>2.5</u>           |
| Type Spillway                          | <u>INCLINED MASONRY WEIR</u> |                      |
| "C" Value - Spillway                   | <u>3.1</u>                   | <u>3.1</u>           |
| Crest Length - Spillway (ft)           | <u>27.2</u>                  | <u>27.2*</u>         |
| Spillway Peak Discharge (cfs)          | <u>204</u>                   | <u>333</u>           |
| Auxiliary Spillway Crest Elevation     | <u>SEE NEXT SHEETS</u>       |                      |
| Auxiliary Spillway Head Available (ft) | <u>          </u>            | <u>          </u>    |
| Type Auxiliary Spillway                | <u>          </u>            | <u>          </u>    |
| "C" Value - Auxiliary Spillway         | <u>          </u>            | <u>          </u>    |
| Crest Length - Auxiliary Spillway (ft) | <u>          </u>            | <u>          </u>    |
| Auxiliary Spillway                     | <u>          </u>            | <u>          </u>    |
| Peak Discharge (cfs)                   | <u>          </u>            | <u>          </u>    |
| Combined Spillway Discharge (cfs)      | <u>          </u>            | <u>          </u>    |

Spillway Rating Curve:

\* DRAWINGS SHOW  
GREATER WIDTH

| Elevation         | Q Spillway (cfs)     | Q Auxiliary Spillway (cfs) | Combined (cfs)    |
|-------------------|----------------------|----------------------------|-------------------|
| <u>          </u> | <u>SEE SHEET C-7</u> | <u>          </u>          | <u>          </u> |
| <u>          </u> | <u>          </u>    | <u>          </u>          | <u>          </u> |
| <u>          </u> | <u>          </u>    | <u>          </u>          | <u>          </u> |
| <u>          </u> | <u>          </u>    | <u>          </u>          | <u>          </u> |
| <u>          </u> | <u>          </u>    | <u>          </u>          | <u>          </u> |
| <u>          </u> | <u>          </u>    | <u>          </u>          | <u>          </u> |
| <u>          </u> | <u>          </u>    | <u>          </u>          | <u>          </u> |

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

1908.9

260'

39'

180

32'

3.75

1907.1

35.45

1907.6

300

53.3

1906.5

Q1

ASSUME CRITICAL

$Q = \sqrt{\frac{A^3 g}{T}}$  AND A

FOR R

DISTANCE COEFF.

HEAD TO WATER SURFACE

$$h v = \frac{v^2}{2g} \quad v = Q/A$$

| WATER SURFACE | AREA      |        | TOPWIDTH |       | $\frac{2.7}{3.1} \sqrt{\frac{A^2 g}{T}}$ | KV | POOL ELEV |
|---------------|-----------|--------|----------|-------|--|----|-----------|
|               | INCREMENT | TOTAL  | INCR.    | TOTAL |  |    |           |
| 1906.5        | 0         | 0      |          |       | 0  | 0  | 1906.5    |
|               | 7.13      |        | 28.5     |       |  |    |           |
| 1907.0        |           | 7.13   |          | 28.5  | 18                                       | .1 | 1907.10   |
|               | 8.14      |        | -        |       |  |    |           |
| 1907.1        |           | 10.27  |          | 34.3  | 28                                       | .1 | 1907.20   |
|               | 16.9      |        | 15.8     |       |  |    |           |
| 1907.5        |           | 27.15  |          | 50.1  | 99                                       | .2 | 1907.7    |
|               | 5.21      |        | 3.9      |       |  |    |           |
| 1907.6        |           | 32.4   |          | 54.0  | 124                                      | .2 | 1907.8    |
|               |           |        |          |       |  |    |           |
| 1908.2        |           | 124.58 |          | 257.3 | 428                                      | .2 | 1908.4    |
|               |           |        |          |       |  |    |           |
| 1910.0        |           | 590.15 |          | 260   | 4393                                     | .9 | 1910.9    |

C-6

GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

MAIN spillway  $Q = 3.1 \times 27.2 \times H^{1.5}$   
 $H = (\text{POOL EL} - 1905.8)$

| POOL EL                   | $Q$<br>AUX SPILL | $Q$<br>MAIN spillway | $\Sigma Q$ |
|---------------------------|------------------|----------------------|------------|
| <u>← PREVIOUS SHEET →</u> |                  |                      |            |
| 1905.8                    | —                | 0                    | 0          |
| 1906.5                    | —                | 49                   | 49         |
| 1907.1                    | 18               | 125                  | 143        |
| 1907.2                    | 28               | 140                  | 168        |
| 1907.7                    | 99               | 221                  | 320        |
| 1907.8                    | 124              | 238                  | 362        |
| 1908.4                    | 428              | 354                  | 782        |
| 1910.9                    | 4393             | 971                  | 5364       |

↑  
LOW AREA BETWEEN  
EMBANKMENTS

OUTFLOW  
RATING  
CURVE

C-7

Data for Dam at Outlet of Subarea A1

Name of Dam: LAKE HENRY Sheet 2 of     

| Outlet Works Rating:                 | <u>Outlet 1</u> | <u>Outlet 2</u>   | <u>Outlet 3</u>   |
|--------------------------------------|-----------------|-------------------|-------------------|
| Invert of Outlet                     | <u>1889.7</u>   | <u>          </u> | <u>          </u> |
| Invert of Inlet                      | <u>1891.4</u>   | <u>          </u> | <u>          </u> |
| Type                                 | <u>CIP</u>      | <u>          </u> | <u>          </u> |
| Diameter (ft) = D                    | <u>2' = 24"</u> | <u>          </u> | <u>          </u> |
| Length (ft) = L                      | <u>200</u>      | <u>          </u> | <u>          </u> |
| Area (sq. ft) = A                    | <u>3.14</u>     | <u>          </u> | <u>          </u> |
| N                                    | <u>.014</u>     | <u>          </u> | <u>          </u> |
| K Entrance                           | <u>0.5</u>      | <u>          </u> | <u>          </u> |
| K Exit                               | <u>1.0</u>      | <u>          </u> | <u>          </u> |
| K Friction* = $29.1 N^2 L / R^{4/3}$ | <u>2.87</u>     | <u>          </u> | <u>          </u> |
| Sum of K                             | <u>4.37</u>     | <u>          </u> | <u>          </u> |
| $(1/K)^{0.5} = C$                    | <u>.48</u>      | <u>          </u> | <u>          </u> |
| Maximum Head (ft) = HM               | <u>17.6</u>     | <u>          </u> | <u>          </u> |
| $Q = C A \sqrt{2g(HM)}$ (cfs)        | <u>51</u>       | <u>          </u> | <u>          </u> |
| Q Combined (cfs)                     | <u>≈ 50</u>     | <u>          </u> | <u>          </u> |

\* R = Hydraulic Radius = (Area/Wetted Perimeter) =  
D/4 for Circular Conduits.



SUSQUEHANNA River Basin

Name of Stream: LAKE RUN

Name of Dam: LAKE HENRY

NDS ID No.: \_\_\_\_\_

DER ID No.: \_\_\_\_\_

Latitude: N 41° 17' 05" Longitude: W 75° 29' 20"

Drainage Area: 0.3 sq. mile

Data for Subarea: A1 (see Sketch on Sheet C-4)

Name of Dam at Outlet of Subarea: LAKE HENRY

Drainage Area of Subarea: 0.3 sq. mile

Subarea Characteristics:

Assumed Losses: 1.0-inch initial abstraction + 0.05 in/hr

The following are measured from outlet of subarea to the point noted:

L = Length of Main Watercourse extended to the divide = 0.91 mile

LCA = Length of Main Watercourse to the centroid = 0.42 mile

From NAB Data: AREA 11 PLATE E

$C_p = \underline{0.62}$  | CENTROID LOCATED IN RESERVOIR → LENGTH RESERVOIR TO DIVIDE =  $0.38 \text{ mi} = L'$   
 $C_T = \underline{1.50}$  |  $T_p = C_T (L')^{0.6}$

$T_p = C_T \times (L \times L_{CA})^{0.3} = \underline{1.12} \text{ (hrs)} = \underline{0.84 \text{ HRS}} \text{ USED}$

Flow at Start of Storm =  $1.5 \text{ cfs/sq. mile} \times \text{Subarea D.A} = \underline{0.5} \text{ cfs}$

Computer Data:

QRCSN = -0.05 (5% of peak flow)

RTIOR = 2.0

Remarks: \_\_\_\_\_

GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

## SELECTED Computer Output

| <u>ITEM</u>           | <u>PAGE</u> |
|-----------------------|-------------|
| Input                 | C-12        |
| SUMMARY OF PEAK FLOWS | C-13        |
| LAKE HENRY DAM        | C-14        |

C-11

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HFC-1)  
 DAM SAFETY VERSION JULY 1976  
 LAST MODIFICATION 26 FEB 76  
 \*\*\*\*\*

| NATIONAL DAM INSPECTION PROGRAM |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
|---------------------------------|----|----|----|-----|----|---|---|---|---|---|---|---|---|---|
|                                 | A1 | A2 | A3 | B   | C  | D | E | F | G | H | I | J | K | L |
| 1                               |    |    |    | 300 | 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2                               |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 3                               |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 4                               |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 5                               |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 6                               |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 7                               |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 8                               |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 9                               |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 10                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 11                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 12                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 13                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 14                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 15                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 16                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 17                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 18                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 19                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 20                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 21                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 22                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 23                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 24                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 25                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 26                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |
| 27                              |    |    |    |     |    |   |   |   |   |   |   |   |   |   |



PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

| OPERATION     | STATION | AREA | PLAN | RATIOS APPLIED TO FLOWS |         |         |         |
|---------------|---------|------|------|-------------------------|---------|---------|---------|
|               |         |      |      | RATIO 1                 | RATIO 2 | RATIO 3 | RATIO 4 |
|               |         |      |      | 1.00                    | .70     | .60     | .50     |
| HYDROGRAPH AT | 1       | .30  | 1    | 1191.                   | 834.    | 715.    | 596.    |
|               | (       | .78) | (    | 33.74)(                 | 23.62)( | 20.24)( | 16.87)( |
| ROUTED TO     | 1       | .30  | 1    | 944.                    | 406.    | 289.    | 221.    |
|               | (       | .78) | (    | 26.74)(                 | 11.50)( | 8.19)(  | 6.26)(  |

# COMPARISON OF SAFETY ANALYSIS

## LAKE HENRY DAM

| PLAN | ELEVATION<br>STATION<br>COORDINATES | INITIAL VALUE<br>1905 AD<br>629.<br>0. | SPILLWAY CREST<br>1905 AD<br>625.<br>0. | TOP OF DAM<br>1907 AD<br>759.<br>290. | DURATION<br>OVER TOP<br>HOURS | MAXIMUM<br>OUTFLOW<br>CFG | MAXIMUM<br>STORAGE<br>AC-FT | MAXIMUM<br>DEPTH<br>FT | MAXIMUM<br>RES. W/UP<br>W. S. CLEV | RATIO<br>OF<br>FOS | TIME OF<br>MAX OUTFLOW<br>HOURS | TIME OF<br>FAILURE<br>HOURS |
|------|-------------------------------------|--|---|---------------------------------------|-------------------------------|---------------------------|-----------------------------|------------------------|------------------------------------|--------------------|---------------------------------|-----------------------------|
|      |                                     |  |   |                                       |                               |                           |                             |                        |                                    |                    |                                 |                             |
| 1.00 | 1907.99                             | .39                                    | 788.                                    | 944.                                  | 3.75                          | 41.00                     | 0.00                        | 0.00                   | 0.00                               | 0.00               | 0.00                            | 0.00                        |
| .70  | 1907.77                             | .17                                    | 771.                                    | 406.                                  | 2.50                          | 42.00                     | 0.00                        | 0.00                   | 0.00                               | 0.00               | 0.00                            | 0.00                        |
| .60  | 1907.56                             | 0.00                                   | 759.                                    | 289.                                  | 0.00                          | 42.50                     | 0.00                        | 0.00                   | 0.00                               | 0.00               | 0.00                            | 0.00                        |
| .50  | 1907.37                             | 0.00                                   | 742.                                    | 221.                                  | 0.00                          | 42.50                     | 0.00                        | 0.00                   | 0.00                               | 0.00               | 0.00                            | 0.00                        |

GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

SUMMARY OF PERTINENT RESULTS  
(DAM WITH EXISTING CONDITIONS)

PMF RAINFALL = 24.9"

|                            | <u>PMF</u> | <u>1/2 PMF</u> |
|----------------------------|------------|----------------|
| RUNOFF (INCHES)            | 23.3       | 11.6           |
| LAKE HENRY DAM             |            |                |
| INFLOW (CFS)               | 1191       | 596            |
| OUTFLOW (CFS)              | 944        | 221            |
| DEPTH OF OVERTOPPING (FT.) | 0.39       | —              |

C-15

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY

PENNSYLVANIA

LAKE HENRY DAM

NDI ID No. PA-00366  
DER ID No. 35-16

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

APRIL 1979

APPENDIX D  
PHOTOGRAPHS

LAKT HENRY DAM



A. Upstream Slope - Right Embankment



B. Outlet Works Outfall

LAKE HENRY DAM



C. Left Embankment - View from Right End



D. Low Area Between Embankments

LAKE HENRY DAM



E. Spillway Approach



F. Spillway

SUSQUEHANNA RIVER BASIN  
LAKE RUN, LACKAWANNA COUNTY  
PENNSYLVANIA

LAKE HENRY DAM

NDI ID No. PA-00366  
DER ID No. 35-16

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

APRIL 1979

APPENDIX E

GEOLOGY



## LAKE HENRY DAM

### APPENDIX E

#### GEOLOGY

1. General Geology. The damsite and reservoir are located in Lackawanna County. Lackawanna County was completely covered with ice during the last continental glaciation of Pleistocene time. The general direction of ice movement was S 35° - 40° W. Glacial drift covers the entire County, except where subsequent erosion has removed it. Thick deposits of glacial outwash occur in many places along the Lackawanna River, and are 50 to 100 feet thick near Dickson, Scranton, and Moosic.


The only important structural feature in Lackawanna County is the Lackawanna Syncline, which traverses the County in a southwesterly direction. The syncline enters the County at the northeast corner as a narrow shallow trough, gradually deepens and broadens toward the southwest, and reaches its maximum development in Luzerne County. The rock formations exposed range from the post-Pottsville formations (youngest) through the Pottsville, Mauch Chunk shale, Pocono sandstone to the Damascus formation of the Catskill group (oldest). The rim rocks, the Pottsville formation and Pocono sandstone, have dips that rarely exceed 10° to 20° and form rather simple syncline. The core rocks, the post-Pottsville formations, are folded into a series of minor anticlines and synclines which trend about N 70° E. The rocks in the northwestern and southeastern parts of the County, outside of the limits of the Lackawanna Syncline, are generally horizontally stratified.

The Lackawanna River, in general, follows the axis of the Lackawanna Syncline. Southeast of the Lackawanna River, the rise in terrain is quite gradual and the crests of the high mountains are several miles from the Lackawanna River. Streams, such as Roaring Brook, Stafford Meadow Brook, and Spring Brook, have cut deep canyons through the mountains and follow a torturous course to their confluence with the Lackawanna River near Scranton. Northwest of the Lackawanna River, the mountains rise abruptly to a sharp ridge which in most places is somewhat higher than the country to the northwest. Consequently, most of the drainage in this part of the County flows westward by way of Tunkhannock

Creek. A few small tributary streams, however, such as Leggetts Creek, flow eastward from this area into Lackawanna River. In the area of interest, the Lackawanna River streambed is founded in post-Pottsville formations. Proceeding uphill from the river, the older Pottsville formation, Mauch Chunk shale, Pocono sandstone, and Catskill continental group are encountered in turn. The tributary streams, in flowing down the mountains, have generally cut through or around the hard sandstone and conglomerate members, and have eroded their streambed into the softer shales and glacial till. The Catskill continental group of rocks underlies the greater part of Lackawanna County.

2. Site Geology. Lake Henry Dam is underlain by the Catskill Formation of late Devonian Age on the Pocono Plateau. The plateau in this area is of very moderate local relief with many swamps and some peat bogs present. The Catskill Formation is composed of dark red shale, claystone and siltstone; gray, fine to medium grained sandstone, and coarse grained conglomerates. Crossbedding, channeling and cut-and-fill features are common to the sandstone and conglomerate units. Siltstone predominates in the lower part of the formation.

The Pennsylvania Water Supply Commission, in their 1914 Report on the dam, considered the information about the dam unreliable. It was reported that the masonry core-wall was founded on a stratified sandstone for a portion of its length and on a clay for the remainder.



LAKE HENRY DAM

ALLUVIUM AND  
GLACIAL OUTWASH

CATSKILL FORMATION

MOSCOW

1 MILE

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
LAKE HENRY DAM  
PENNSYLVANIA GAS AND WATER COMPANY

GEOLOGIC MAP

APRIL 1979

PLATE E-1